

*Inspection Photos*  
*Loc#323941*  
*Operator: Caerus*  
*Inspection #: 692402645*  
*Inspection Date: 10/30/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry to North.

October 30,, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus KRK Loc#323941





Photo#2:  
View over equipment.



Photo#3:  
View over Interim.

October 30,, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus KRK Loc#323941