

BP L48 San Juan



V2 Compliance Follow Up Form

18158332837

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20201013-18158332837

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Oct 13, 2020 8:29:29 AM MDT

91 S Skylane Dr, Durango, CO 81303, USA

Oct 13, 2020 8:29:01 AM MDT [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Oct 9, 2020

Well Name

MCKEEN GAS UNIT 32-6-15 1

API Number

50670754400

Select State

Colorado

Work type

BP call out

Action Complete

Clean Up Weed Debris

Photo of first corrective action completed



**Completed work description Corrective
Action 1**

location sign

Photo of second corrective action completed



**Completed work description of corrective
action 2**

removed debris away from equipment

Photo of third corrective action completed



Completed work description of corrective action 3

before removal

Photo of fourth corrective action completed



Completed work description

after removal

Completed work description of corrective action 4

removed weed debris from location

Additional photos



Additional photos**Additional photos****Additional photos****Completed work description**

removed weed debris from location

Summary of all work completed

previous treatment dates 7/7/16, 7/28/17,
5/22/18, 4/4/19, 6/9/20