

**Inspection Photos**  
**Operator: BP America**  
**API: 067-08414**  
**Date: 11/10/2020**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is largely grazed with grasses such as smooth brome and sand dropseed observed. A single trailer stored in the southwestern project area.



Photo 3. View of musk thistles within the southwestern project area. Approximately 200 musk thistles observed.



Photo 4. View of reference area comprised of irrigated grass field, largely snow covered at this time.