

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /17SWSW

Location ID: 334066



Photo #2229 from entrance to location.



Photo #2230 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC ORCHARD UNIT-68S96W /17SWSW

Location ID: 334066



**Photo #2231 Braden head valves are not accessible on well 17-14A.**