

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402478035

Date Received:

08/31/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46685

Name of Operator: KINDER MORGAN CO2 CO LP

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Jake Forsman

Phone

970-882-5541

Email

jake\_forsman@kindermorgan.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700300068

Inspection Date: 08/19/2020

FIR Submit Date: 08/24/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LP

Company Number: 46685

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 313469

Location Name: MCELMO DOME UNIT 26-38-18-N38N18W Number: 26SENW County: MONTEZUMA

Qtrqtr: SENW Sec: 26 Twp: 38N Range: 18W Meridian: N

Latitude: 37.524157 Longitude: -108.803256

FACILITY - API Number: 05-083-00 Facility ID: 224135

Facility Name: MCELMO DOME UNIT 26-38-18 (EPA) Number: YWD-1

Qtrqtr: SENW Sec: 26 Twp: 38N Range: 18W Meridian: N

Latitude: 37.524157 Longitude: -108.803256

CORRECTIVE ACTIONS:

1 ☒ CA# 141425

Corrective Action: Comply with Rule 1204.a(1) (note: better container will help with loose trash)

Date: 09/01/2020

Also ensure proper disposal of E&P waste (filters)

Response: CA COMPLETED

Date of Completion: 08/28/2020

Operator  
Comment:

The open-top solid waste dumpster at the YWD-1 location was replaced with a bear-proof solid waste dumpster on 08/28/2020.

The corrective action included the comment "Also ensure proper disposal of E&P waste (filters)". KM manages

the injection well filters as solid waste along with other solid waste generated at the injection well locations. Samples of spent filters from KM injection well locations were sent to a laboratory for analysis of BTEX/TPH, TCLP Metals and Hazardous Characteristics (Reactivity/Corrosivity/Ignitability) and a paint filter test. The results of analyses showed that the filters do not display any concentrations of hazardous characteristics, toxic metals or volatile organic compounds that exceed RCRA Subtitle C thresholds or COGCC Table 910-1 standards (soil). The results of analyses, along with the results of the paint filter test, were requested by and submitted to the Montezuma County Landfill in order for the filters to be accepted for disposal as solid waste. The spent filters are dried completely before being placed in the dumpster.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jake Forsman

Signed: \_\_\_\_\_

Title: EHS Specialist

Date: 8/31/2020 3:26:21 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <b><u>Document Number</u></b> | <b><u>Description</u></b> |
|-------------------------------|---------------------------|
| 402478035                     | FIR RESOLUTION SUBMITTED  |
| 402478045                     | Photo Log                 |

Total Attach: 2 Files