

Inspection Photos

Operator: BP America
API: 067-09190
Date: 11/10/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of dense Russian knapweeds along the pipeline ROW. Thousands of individuals observed.



Photo 3. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with grasses such as crested wheatgrass, intermediate wheatgrass, and sand dropseed.



Photo 4. View of reference area, grass field, largely snow covered at this time.