

# Inspection Photos

Operator: BP America  
API: 067-07010  
Date: 11/10/2020



Photo 1. View of the project area from the northwestern well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Wood beams stored in the northern project area.





Photo 3. View of the eastern project area from the northeastern corner facing southward. What appears to be landowner trailer remains in the eastern project area. Approximately 200 musk thistles observed.





Photo 4. Another view of dense musk thistles within the project area.





Photo 5. View of reference area (beyond road), comprised of irrigated grass field which is largely snow covered at this time.