

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402533561

Date Received:
11/16/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10531
Name of Operator: GRIZZLY OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>.Grizzly</u>		<u>aaxelson@grizzlyenergyllc.com</u>
<u>.Grizzly</u>		<u>sghan@grizzlyenergyllc.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 700701837
Inspection Date: 11/05/2020 FIR Submit Date: 11/05/2020 FIR Status: _____

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC Company Number: 10531
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 335501

Location Name: DOMMER-66S92W Number: 26NWSE County: _____
Qtrqtr: NWSE Sec: 26 Twp: 6S Range: 92W Meridian: 6
Latitude: 39.497430 Longitude: -107.633130

FACILITY - API Number: 05-045-00 Facility ID: 335501

Facility Name: DOMMER-66S92W Number: 26NWSE
Qtrqtr: NWSE Sec: 26 Twp: 6S Range: 92W Meridian: 6
Latitude: 39.497430 Longitude: -107.633130

CORRECTIVE ACTIONS:

1 CA# 144191

Corrective Action: Provide egress for wildlife Date: 11/26/2020

Response: CA COMPLETED Date of Completion: 11/16/2020

Operator Comment: Ramp installed.

COGCC Decision: _____

Date: 11/26/2020

Date of Completion: 11/11/2020

Raked and seeded.

COGCC Decision: _____

--

--

Signed:

Date: 11/16/2020 1:56:09 PM

--	--

Page 2 of 2