

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Vega /2 Pad

Location ID: 334452



**Photo #2237 from entrance to location.**



**Photo #2238 from entrance to location.**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC Vega /2 Pad

Location ID: 334452



**Photo #2239 Tank burner assembly missing bird protector.**