

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /2-6H (PL35NW)

Location ID: 424424



Photo #2255 from entrance to location.



Photo #2256 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /2-6H (PL35NW)

Location ID: 424424



Photo #2257 Multiple places with debris on location.



Photo #2258 Multiple places with debris on location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC Federal /2-6H (PL35NW)

Location ID: 424424



Photo #2259 Sediment migrating off of location and on to access road due to tracking.



Photo #2260 Access road.