

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402535567

Date Received:
11/18/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
.		<u>NBL_DJBU_Inspections@NBLENERGY.COM</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696302665

Inspection Date: 11/16/2020

FIR Submit Date: 11/17/2020

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 326772

Location Name: LILLI UNIT-68N58W Number: 8NWNE County: WELD

Qtrqr: NWNE Sec: 8 Twp: 8N Range: 58W Meridian: 6

Latitude: 40.682200 Longitude: -103.884110

FACILITY - API Number: 05-123-00 Facility ID: 245843

Facility Name: LILLI UNIT Number: 2-8

Qtrqr: NWNE Sec: 8 Twp: 8N Range: 58W Meridian: 6

Latitude: 40.682200 Longitude: -103.884110

CORRECTIVE ACTION:

1 CA# 144404

Corrective Action: Comply with Rule 603.f.

Date: 12/02/2020

Response: CA COMPLETED

Date of Completion: 11/18/2020

Operator Comment: The unused parts have been removed.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 144405

Corrective Action: Comply with Rule 603.f.

Date: 11/20/2020

Response: CA COMPLETED

Date of Completion: 11/18/2020

Operator
Comment: We ensured the OOSLAT tag was visible.

COGCC Decision: _____

COGCC
Representative: _____

3 CA# 144406

Corrective Action: For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 907.e."
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 12/02/2020

Response: CA COMPLETED

Date of Completion: 11/18/2020

Operator
Comment: The stained soil has been removed and properly disposed of.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Specialist

Date: 11/18/2020 1:47:36 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files