

BP L48 San Juan



V2 Compliance Follow Up Form

18162091835

Reference Number:

20201112-18162091835

Form Name:

V2 Compliance Follow Up Form

Submitter Name:

Cole Nichols (colen@horizonenvservices.com) |
colen@horizonenvservices.com

Submission Date:

Nov 12, 2020 2:28:35 PM MST

Location:

91 S Skylane Dr, Durango, CO 81303, USA

Nov 12, 2020 2:31:28 PM MST [[View Map](#)]

INFORMATION

Section 1

Name	colen@horizonenvservices.com
Date	Nov 11, 2020
Well Name	PAYNE, EVELYN GAS UNIT A 1
API Number	50670677800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Seeding Erosion Repairs

Photo of first corrective action completed



**Completed work description Corrective
Action 1**

location sign

Photo of second corrective action completed



**Completed work description of corrective
action 2**

repaired rills and seeded/blanketed slope

Photo of third corrective action completed



**Completed work description of corrective
action 3**

seeded and blanketed slope

Photo of fourth corrective action completed



Completed work description

seeded and blanketed slopes

Completed work description of corrective action 4

repaired rills and seeded and blanketed slopes

Additional photos



Additional photos



Completed work description

seeded and blanketed slopes

Summary of all work completed

repaired rills, seeded and blanketed slopes