

# Inspection Photos

Operator: BP America  
API: 067-06657  
Date: 11/17/2020



Photo 1. View of the project area from the northwestern corner facing center.





Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing with grasses such as smooth brome, western wheatgrass, and thickspike wheatgrass.





Photo 3. View of Russian knapweed within the southern project area. Approximately 200 individuals observed.





Photo 4. View of the reference area comprised of pinyon juniper woodland with gambel oak, sagebrush, western wheatgrass, and blue grama.