

Inspection Photos
Location Name: Dwinell 610N79W 23SESW
Location ID: 324590



Photo 1. Stained soil in tank battery.



Photo 2. Stained soil in tank battery.



Inspection Photos
Location Name: Dwinell 610N79W 23SESW
Location ID: 324590



Photo 3. Stained soil in tank battery.



Photo 4. Stained soil in tank battery.



Inspection Photos
Location Name: Dwinell 610N79W 23SESW
Location ID: 324590



Photo 5. Leak occurring at bolted tank. Dark soil is wet from leaking fluid.



Photo 6. Close up of ongoing leak from photo 5.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources