

Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Tank battery Sign.



Unmarked flowline risers.

Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Exposed flowlines.



Exposed flowlines.

Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID:
115239



Exposed flowlines.



Unused equipment.



Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Unused equipment (hoses) and material generated from remediation efforts.



Unused equipment.

Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Oil impact material from Spill ID 473059 discovered on 03/09/2020.



Hoses, debris, and weeds.



Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Unlabeled but placard tank. Contents unknown.



Unlabeled but placard tank. Contents unknown.

Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Recent reworking of berm area and suspected recently constructed fireline.



Oil impacts from Spill ID 473059 discovered on 03/09/2020. Oily material is being tracked across location recently constructed fireline.

Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Unused equipment and debris. Impacted material from Spill ID 473059.



Unused equipment and debris. Impacted material from Spill ID 473059.



Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Trash/debris.

Trash/debris. Note metal fence post.



Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID:
115239



Weeds.

Weed and debris.

Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Apparent recently constructed fireline around location.



Apparent recently constructed fireline around location.

Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Pit Facility ID: 115239



Unused flowline.

Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID:
115239



Bell hole dug in base of pit. Visual hydrocarbon impacts.



Unused equipment and trash.



Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Unused equipment and trash.



Burrow within secondary containment berm.

Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239




Weeds, trash, and debris.

Un marked flowline risers, trash, and debris.

Inspection Photos October 14, 2020

Location Name: Dwinell Tank Battery Location ID: 324591; Spill ID: 473059; REM 15326; Pit ID: 115239



Oily soil.



Oily soil.