

Final Reclamation Inspection

November 12, 2020

Operator: Erie Town - 100547

Location ID: 321328

Inspection Document #: 697502191

Boulder County, CO

NENW Section 34 T1N R69W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ADAMS #1
Location ID: 321328



Photo 1. Photo taken from the entrance of the location off Hwy 287, facing West. Photo illustrates the Operator has failed to perform final reclamation activities.



Photo 2. Photo taken from the entrance of the location off Hwy 287, facing East. See comments under Photo 1.

Inspection Photos
Location Name: ADAMS #1
Location ID: 321328



Photo 3. Photo taken from the location, facing South. Photo illustrates the Operator has failed to perform final reclamation activities and failed to manage noxious weeds.



Photo 4. Photo taken from a portion of the location. Photo illustrates a Musk thistle, List B, Colorado noxious weed.

Inspection Photos
Location Name: ADAMS #1
Location ID: 321328



Photo 5. Photo taken from the location, facing West. See comments under Photo 3-4.




Photo 6. Photo taken from the location, facing East. See comments under Photo 3-4. Photo also illustrates a mat of Puncture vine, List C, Colorado noxious weed.



Photo 7. Reference vegetation photo taken north of the location entrance, facing Northwest.