

# *Inspection Photos*

*Loc#438248*

*Operator: SWN*

*Insp#: 692402688*

*Insp Date: 11/18/2020*



Photo#1:  
View of Location from entry to Northwest.

November 18, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: SWN Diamond T Sheep Loc#438248



Photo#2:  
Overview of Location from Southwest corner to Northeast.

November 18, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: SWN Diamond T Sheep Loc#438248





Photo#3:  
Senesced weeds on un-trafficked areas of pad.



Photo#4:  
Senesced weeds on berms.

November 18, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: SWN Diamond T Sheep Loc#438248



**Photo#5:**  
Scotch thistle, Cheat grass on Fill slopes, in BMPs.



**Photo#6:**  
Scotch thistle, Cheat grass on Fill slopes, in BMPs.

November 18, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: SWN Diamond T Sheep Loc#438248





Photo#7:  
Staining on Location.



Photo#8:  
Staining on Location.

November 18, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: SWN Diamond T Sheep Loc#438248



Photo#9:  
Unused equipment on Location.

November 18, 2020





Photo#10:  
2015 COGCC Maps Aerial image of Location.



Photo#11:  
2019 COGCC Maps Aerial image of Location

November 18, 2020