

Final Reclamation Inspection

November 12, 2020

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 318767

Inspection Document #: 697502199

Weld County, CO

SESW Section 10 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: UPRR 43 PAN AM I #28-X
Location ID: 318767



Photo 1. Photo taken from the southern access road, facing North. Photo illustrates the access road has reflective establishment of crop (i.e., winter wheat).

Inspection Photos
Location Name: UPRR 43 PAN AM I #28-X
Location ID: 318767



Photo 2. Photo taken from the well location, facing South. Photo illustrates the well location has reflective establishment of crop (i.e., winter wheat).