

Inspection Photos

11/19/2020

Operator: SG INTERESTS I LTD # 77330

Location ID: 428197

Gunnison, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 428197



Photo 1: Photo taken from the northwest corner of the Location, facing east. Photos 1-2 provide an overview of the Location from east to southeast.



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 428197



Photo 3: Photo taken from the fill slopes on the north end of the Location. Photo shows Musk thistle is evident on the Location. Due to the onset of winter conditions and plant dormancy, a followup inspection will need to be conducted in the 2021 growing season to determine compliance with Rule 1003.f.



Photo 4: Photo taken from the northeast corner of the Location. Photo erosion degradation on the cut slopes of the Location. Photo shows that long-term erosion control BMPs do not appear to have been installed in conjunction with the erosion matting, appears insufficient and/or has not been maintained in a proper functioning condition.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 428197



Photo 5: Photo taken from the northeast corner of the Location. Photo erosion degradation on the cut slopes of the Location. Photo shows that long-term erosion control BMPs do not appear to have been installed in conjunction with the erosion matting, appears insufficient and/or has not been maintained in a proper functioning condition.



Photo 6: Photo taken from the northeast corner of the Location. Photo erosion degradation on the cut slopes of the Location. Photo shows that long-term erosion control BMPs do not appear to have been installed in conjunction with the erosion matting, appears insufficient and/or has not been maintained in a proper functioning condition.

Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 428197



Photo 7: Photo shows sign located at the tank battery identifying that Location has a delayed IR variance until 5/31/2022



Photo 8: Photo shows the single drilled well on the Location.



Inspection Photos
Operator Name: SG INTERESTS I LTD # 77330
Location ID: 428197




Photo 9: Photo taken from the PR well. Photo shows cellar at wellhead.



Photo 10: Continued from photo 9. Photo shows cellar has filled with fluids/chemicals, BMPs to prevent wildlife access to the cellar are insufficient.