

Inspection Photos  
Location Name: Simpson 26 Pad  
Location ID: 457767



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos  
Location Name: Simpson 26 Pad  
Location ID: 457767



**Photo 3: No BBLS or NFPA placard**



**Photo 4: No BBLS or NFPA placard**

Inspection Photos  
Location Name: Simpson 26 Pad  
Location ID: 457767



Photo 5: No NFPA placarding



Photo 6: No NFPA placarding

Inspection Photos  
Location Name: Simpson 26 Pad  
Location ID: 457767



Photo 7: No NFPA placarding



Photo 8: No NFPA placarding

Inspection Photos  
Location Name: Simpson 26 Pad  
Location ID: 457767



**Photo 9: Inadequate berm surrounding tank battery**



**Photo 10: Separator not anchored**