

Inspection Photos
Location Name: T&M DE Pad 22-039HC
Location ID: 446023



Photo 1: Tank Battery Signs



Photo 2: Wellheads



Inspection Photos
Location Name: T&M DE Pad 22-039HC
Location ID: 446023



Photo 3: No NFPA placard



Photo 4: No NFPA placard

Inspection Photos
Location Name: T&M DE Pad 22-039HC
Location ID: 446023



Photo 5: No NFPA placard



Photo 6: No NFPA placard



Inspection Photos
Location Name: T&M DE Pad 22-039HC
Location ID: 446023



Photo 7: No NFPA placard