

Pit Status Evaluation Form

Pit Overview:

Pit Name: OKARSON 1	Facility ID: 118399
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: VESSELS OIL & GAS COMPANY / 93200	
Updated Operator:	
Form 15 Pit Permit Doc #: 712502	Permit Date: 11/14/1977
Related Facilities: OSKARSON #1 (API 123-09026, Facility ID 241238; Loc ID 333130)	

County: WELD			
Township: 2N	Range: 68W	Section: 33	QQ: SESW
Original Latitude/ Longitude: 40.089297 / -105.010636			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|--|------------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 712502 | Date: 11/14/1977 |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 500163896 | Date: 8/27/1997 |
| | Doc #: 200027884 | Date: 6/24/2002 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input checked="" type="checkbox"/> | COGIS Document – Doc #: 574726 | Date: 3/1/1995 |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2314546 | Date: 12/18/1995 |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 103632, 103633, 103631 (shared battery) | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input checked="" type="checkbox"/> | Other: Pit Inventory Doc# 2223816 - 1/21/1997 | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Replaced by cement tank prior to 1995 pit inventory report.

Pit Status Review Summary:

Based on records review and aerial imagery any pits on location were replaced by a tank prior to 1995 pit inventory report. Pit inventories and inspections document a cement tank on location (shared battery Oskarson 1-4; duplicate Pit IDs 118399, 103631-3). Pit Status has been changed to closed.

