

Inspection Photos
Location Name: McCallum 151
Location ID: 324719



Photo 1. Overview of location taken facing south.



Photo 2. No bradenhead access apparent.