

Pit Status Evaluation Form

Pit Overview:

Pit Name: KIRKMEYER	Facility ID: 118725
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: AMOCO PRODUCTION COMPANY / 2500	
Updated Operator:	
Form 15 Pit Permit Doc #:	Permit Date:
Related Facilities: J.E. KIRKMEYER #1 (API 123-09974; Facility ID 242183; Loc ID 318799)	

County: WELD			
Township: 1N	Range: 67W	Section: 30	QQ: NENW
Original Latitude/ Longitude: 40.027458 / -104.935534			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---------------------------------------------|-----------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 55169 | Date: 1/17/1995 |
| | Doc #: 500165003 | Date: 2/11/1994 |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input checked="" type="checkbox"/> | COGIS Document – Doc #: 55170 | Date: 2/25/1992 |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Closed prior to 1995 field inspection.

Pit Status Review Summary:

Records review and found no evidence of any pits on location; 1995 field inspection documents that produced water at this location goes to a tank. Pit status has been changed to closed.