

Inspection Photos

Loc#433805

Operator: SWN

Insp#: 692402719

Insp Date: 11/20/2020



Photo#1:

Overview of Location to Southwest. Note Senesced weeds and vegetation on un-trafficked areas of pad.

November 20, 2020



Photo#2:

Weedy area at southwest corner of Location. Scotch thistle circled; insert Canada thistle.

November 20, 2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SWN Bulldog Loc#433805



Photo#3:
Weedy & sparsely vegetated areas.



Photo#4:
Weedy & sparsely vegetated areas.

November 20, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SWN Bulldog Loc#433805



Photo#5:
Senesced vegetation in and around equipment areas.



Photo#6:
Open Casing/Rat hole.

November 20, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: SWN Bulldog Loc#433805