

Inspection Photos

API: 071-07489

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/30/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07489 | Date: 11/30/2020

Inspection Photos



Photo 1. Facing southeast along the main road. The location is at the top of the photo. The red arrow points to 4.5 ft. shovel placed in erosion channel next to the road. Stormwater directed from the location has caused erosion in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07489 | Date: 11/30/2020

Inspection Photos



Photo 2. There is erosion occurring at the culvert outlet on the main road near the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07489 | Date: 11/30/2020

Inspection Photos



Photo 3. Facing northeast at the access road. Stormwater directed from the location is causing erosion shown in photo 1



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07489 | Date: 11/30/2020

Inspection Photos



Photo 4. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07489 | Date: 11/30/2020

Inspection Photos



Photo 4. There is erosion rilling occurring along the fill slope of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07489 | Date: 11/30/2020