

Inspection Photos

Loc#463987

Operator: Sandridge

Insp#: 692402699

Insp Date: 11/19/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to East. Insert entry off HWY.

November 19,, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge PRU Alcorn Loc#463987



Photo#2:
Debris weeds are growing outside of and on perimeter berms.

November 19,, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#3:
Debris weeds are growing outside of and on perimeter berms

Inspection Photos: Sandridge PRU Alcorn Loc#463987



Photo#4:
Staging area at West side of site.

Photo#5:
North end of Staging area where stockpiles are stored.

November 19., 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge PRU Alcorn Loc#463987