

**URSA
Burckle A
Location # 335540**



location



location

URSA
Burckle A
Location # 335540

Dec 2, 2020 at 12:11:33 PM
39.525062,-107.670386 ±4.73m
COGCC



location

Dec 2, 2020 at 12:10:32 PM
39.524874,-107.670402 ±4.72m
COGCC




Debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**URSA
Burckle A
Location # 335540**



Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**URSA
Burckle A
Location # 335540**



Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

URSA
Burckle A
Location # 335540



Drain inlet south east side of pad



Drain inlet marked with arrow



**URSA
Burckle A
Location # 335540**



Drain inlet by tank battery south east corner of pad



Drain outlet south east corner of pad

