

Inspection Photos  
Location Name: Heyde NE-26  
Location ID: 319480



Photo #1 Well

Photo #2 P/A


**Inspection Photos**  
**Location Name: Heyde NE-26**  
**Location ID: 319480**



**Photo #3 Production Equipment**

**Photo #4 Tank Battery**

Inspection Photos  
Location Name: Heyde NE-26  
Location ID: 319480



**Photo #5 Gas Meter appears to have no calibration documentation. Measure gas per Rule 329.**