

Inspection Photos

Loc#458558

Operator: Sandridge

Insp#: 692402700

Insp Date: 11/19/20





Photo#1:
Overview of Location from access road to West.

November 19., 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Marmot Loc#458558



Photo#2:
View along East side of Location.

Photo#3:
BMP installed in Southwest berm.

November 19., 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Marmot Loc#458558



Photo#4:
Topsoil stockpile at South end of site.

November 19., 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Marmot Loc#458558