

Inspection Photos

12/1/2020

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 315237

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 315237



Photo 1: Photo taken from the east end of the Location, facing south. Photos 1-4 provide an overview of the Location from south, southwest, northwest to north. Photos also show remediation efforts appear to be ongoing at the form tank, heater treater and pit areas. Location remains out of compliance with Rules.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



Photo 2: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



Photo 3: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



Photo 4: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



Photo 5: Photo taken from the pit on the west end of the Location. Remediation of pit in process. See project #15643 for additional details.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



Photo 6: Photo taken from the pit on the west end of the Location. Remediation of pit in process. See project #15643 for additional details.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



Photo 7: Photo taken from the northwest corner of the Location, facing east. Photo shows BMPs are missing to prevent off-site sediment transport of potentially impacted soils from the stockpiles.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



Photo 8: Photo taken from the northwest corner of the Location, facing south. Photo shows BMPs are missing to prevent off-site sediment transport of potentially impacted soils from the stockpiles.

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 315237



Photo 9: Photo taken from the west end of the Location. Photo shows oil stained soils observed at the soil stockpiles.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources