

Inspection Photos

12/1/2020

Operator: RIO MESA RESOURCES INC - 74740

Location ID: 314650

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: RIO MESA RESOURCES INC - 74740

Location ID: 314650



Photo 1: Photo taken from the north end of the Location, facing south. Photo shows work to remove the stained soils appears to have been conducted. However, unable to find evidence that reseeding/revegetation activities to reclaim the disturbed have been conducted. BMPs to stabilize soils also not observed.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314650



Photo 2: Photo taken from the east end of the Location, west south. Photo shows work to remove the stained soils appears to have been conducted. However, unable to find evidence that reseeding/revegetation activities to reclaim the disturbed have been conducted. BMPs to stabilize soils also not observed.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314650



Photo 3: Photo taken from the slopes observed in photo 1 and 2. Photo shows soil surface. Unable to find evidence that reseeding/revegetation activities to reclaim the disturbed have been conducted. BMPs to stabilize soils also not observed.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314650



Photo 4: Photo taken from the south end of the Location, facing north. Photo shows one of the two cables remaining on the Locaiton.

Inspection Photos
Operator Name: RIO MESA RESOURCES INC - 74740
Location ID: 314650



Photo 5: Photo taken from the south end of the Location, facing west. Photo shows second cable observed on Location.