

# Inspection Photos

12/1/2020

Operator: C & J FIELD SERVICES - 10027

Location ID: 314281

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: C & J FIELD SERVICES - 10027  
Location ID: 314281



**Photo 1:** Photo taken from the south end of the Location, facing north. Photo provides an overview of the Location and reclamation area.

Inspection Photos  
Operator Name: C & J FIELD SERVICES - 10027  
Location ID: 314281



**Photo 2:** Photo taken from the west end of the Location, facing northeast. Photo provides an overview of the Location and reclamation area. Photo also shows weedy vegetative establishment on the reclamation area. Continue conducting weed management on the Location until final reclamation has passed.

Inspection Photos  
Operator Name: C & J FIELD SERVICES - 10027  
Location ID: 314281



**Photo 3:** Photo taken from the southeast end of the Location. Photo shows electric equipment remains on the Location.

Inspection Photos  
Operator Name: C & J FIELD SERVICES - 10027  
Location ID: 314281



**Photo 4:** Photo taken from the access road, facing south. Photo shows flowline/riser equipment remaining.

Inspection Photos  
Operator Name: C & J FIELD SERVICES - 10027  
Location ID: 314281



**Photo 5:** Continued from photo 4. Photo shows leaking from the flowline remains evident. Maintenance to prevent failures or leakage has not been conducted

Inspection Photos  
Operator Name: C & J FIELD SERVICES - 10027  
Location ID: 314281



**Photo 6:** Photo taken from the access road north of the Location, facing south. Photo shows that a portion of the access road between the turn-off and the Location has not been reclaimed per corrective actions and rules. Vehicle travel over the reclamation area evident; Continued vehicle use is not conducive to reclamation.