

URSA
Gentry E
Location # 335547



location



location

URSA
Gentry E
Location # 335547



location



Lack of stabilization



URSA
Gentry E
Location # 335547




Lack of stabilization



Lack of stabilization



URSA
Gentry E
Location # 335547



Lack of stabilization behind tank battery



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

URSA
Gentry E
Location # 335547



Lack of stabilization

