

**Inspection Photos**  
**Location Name: Living 7-7**  
**Location ID: 327473**



**Photo 1 – Well Plugged and Abandoned, Flowline Riser remains**



**Photo 2 – Unused Heater Treater and Vertical Separator**

**Inspection Photos**  
**Location Name: Living 7-7**  
**Location ID: 327473**



**Photo 3 – Tank Battery**



**Photo 4 – Gas Meter**



Inspection Photos  
Location Name: Living 7-7  
Location ID: 327473



Photo 5 – Gas Meter



Photo 6 – Tank Battery Sign

**Inspection Photos**  
**Location Name: Sifkin 11-30H**  
**Location ID: 424135**



**Photo 7 – Holes in Pit Netting fixed**



**Photo 8 – Pit Area**