

Inspection Photos
Location Name: Pergamos 3-44-7-60
Location ID: 424238



Colorado Oil and Gas Conservation Commission
40.59783, -104.07001, 4867.3ft, 192°
12/02/2020 14:18:26

Photo 1 – Tank Battery



Colorado Oil and Gas Conservation Commission
40.5976, -104.07004, 4870.2ft, 154°
12/02/2020 14:18:45

Photo 2 – Tank Battery Sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pergamos 3-44-7-60
Location ID: 424238




Photo 3 – Unused ECD




Photo 4 – Unused Automation Parts



Inspection Photos
Location Name: Pergamos 3-44-7-60
Location ID: 424238



Photo 5 – Stained Soil at Gas Engine




Photo 6 – Flare – Stained Soil at Exhaust



Location ID: 424238

Colorado Oil and Gas Conservation Commission
40.59741, -104.06986, 4849.8ft, 280°
12/02/2020 14:22:39

Photo 7 – Gas Meter Calibration Card

Colorado Oil and Gas Conservation Commission
40.59741, -104.06986, 4849.8ft, 279°
12/02/2020 14:22:45

Photo 8 – Gas Meter Calibration Card