

## Inspection Photos

Location Name: CC 0697-16-16 Pad

Location ID: #335844

Inspection Date: December 4, 2021



Photo #1 – Sign located at entrance to pad.



Photo #2 – View of tank battery from southeast.



Inspection Photos  
Location Name: CC 0697-16-16 Pad  
Location ID: #335844  
Inspection Date: December 4, 2021



Photo #3 – NFPA placard peeling from tank (1).



Photo #4 - NFPA placard peeling from tank (2).



## Inspection Photos

Location Name: CC 0697-16-16 Pad

Location ID: #335844

Inspection Date: December 4, 2021



**Photo #5 - Accumulation of ice inside of tank battery secondary containment area.**



**Photo #6 – View of separators and tank storage area from south.**



## Inspection Photos

Location Name: CC 0697-16-16 Pad

Location ID: #335844

Inspection Date: December 4, 2021



Photo #7 – 2019 aerial photo depicting tank storage area north of pad.



Photo #8 – Tank in tank storage area lacks access panel cover.

