

Inspection Photos
Operator: BP America
API: 067-06559
Date: 12/7/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope, facing eastward. Revegetation is progressing with crested wheatgrass, western wheatgrass, intermediate wheatgrass, and sand dropseed.



Photo 3. View of Russian thistle debris within the southern project area.



Photo 4. View of musk thistle rosettes within the southern project area.



Photo 5. View of Russian knapweeds (approximately 200) within the southeastern project area.



Photo 6. View of the reference area comprised of sagebrush shrubland and pinyon/juniper woodland with understory of squirreltail, blue grama, and penstemon spp.



Photo 7. View of closed gate after leaving location.