

Grizzly Operating Brynildson 13C Location # 335379

Dec 8, 2020 at 9:44:25 AM
39.510817,-107.697089 ±4.74m
OGCC



location

Dec 8, 2020 at 9:42:33 AM
39.510276,-107.697623 ±4.76m
OGCC



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Brynildson 13C Location # 335379



location



Lack of stabilization/erosion is under mining
waddles



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Brynildson 13C Location # 335379



Lack of stabilization/erosion is present along with undermining of combustor pad



Lack of stabilization/erosion is present along with undermining of combustor pad



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Brynildson 13C Location # 335379



Lack of stabilization



Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Brynildson 13C Location # 335379



Lack of stabilization



Lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Grizzly Operating Brynildson 13C Location # 335379



Waddles need maintained



Waddles need maintained



**Grizzly Operating
Brynildson 13C
Location # 335379**



Waddles need maintained



Waddles need maintained

