

Inspection Photos

12/8/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 335091

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335091



Photo 1: Photo taken from the south end of the Location, facing North. Photo provides an overview of the production area.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335091



Photo 2: Photo taken from the south end of the Location, facing northeast. Photo shows BMPs to stabilize and protect cut slopes remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335091



Photo 3: Photo taken from the north end of the Location, facing east. Photo shows BMPs to stabilize and protect cut slopes remain missing or insufficient. .



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335091



Photo 4: Photo taken from the east end of the Location, facing east. Photo shows BMPs to stabilize and protect cut slopes remain missing or insufficient.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335091



Photo 5: Photo taken from the east end of the Location, facing east. Photo shows BMPs to stabilize and protect cut slopes remain missing or insufficient.



Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 335091



Photo 6: Photo taken from the east end of the Location, facing northeast. Photo shows BMPs to stabilize and protect cut slopes remain missing or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 335091



Photo 7: Photo taken from the southeast end of the Location, facing northeast. Photo shows BMPs to stabilize and protect cut slopes remain missing or insufficient.