

Inspection Photos

API: 05-061-06882

Operator: CHESAPEAKE OPERATING LLC

Inspection Date: 12/8/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06882 | Date: 12/8/2020

Inspection Photos



Photo 1. Facing west at the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06882 | Date: 12/8/2020

Inspection Photos




Photo 2. Facing northwest toward the location. The location has been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06882 | Date: 12/8/2020

Inspection Photos



Photo 3. Facing west at the south side of the location. Straw mulch has been crimped into the soil.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06882 | Date: 12/8/2020

Inspection Photos



Photo 4. Facing north at east side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06882 | Date: 12/8/2020

Inspection Photos



Photo 5. Facing west at center of the location. This area was not disturbed due to existing vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06882 | Date: 12/8/2020

Inspection Photos



Photo 6. Facing west at the north side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06882 | Date: 12/8/2020