

Inspection Photos

Location Name: LARAMIE ENERGY LLC Nichols /24-06A Pad

Location ID: 450791



Photo #2419 from entrance to location.



Photo #2420 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Nichols /24-06A Pad

Location ID: 450791



Photo #2421 Sediment is being transported off of location



Photo #2422 Sediment is being transported off of location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Nichols /24-06A Pad

Location ID: 450791



Photo #2423 entrance to location.