

Inspection Photos

Location Name: LARAMIE ENERGY LLC Nichols /24-06 Pad

Location ID: 334504



Photo #2424 from entrance to location



Photo #2425 from entrance to location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Nichols /24-06 Pad

Location ID: 334504



Photo #2426 Sediment is being transported off of location



Photo #2427 Sediment is being transported off of location

Inspection Photos

Location Name: LARAMIE ENERGY LLC Nichols /24-06 Pad

Location ID: 334504



Photo #2428 Access road



Photo #2429 Sediment is being transported off of location