

Inspection Photos

12/8/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 383337

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 1: 2019 COGIS Aerial imagery. Photo shows areas not reasonably needed for production on the Location have not been reclaimed.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 2: Photo taken from the northwest end of the Location, facing northeast. Photos 2-5 provide an overview of the Location from northeast, east, southeast to southwest. Photos also show areas not reasonably needed for production on the Location have not been reclaimed.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 3: See comments under photo 2.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 4: See comments under photo 2.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 5: See comments under photo 2.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 6: Photo taken from the southeast end of the Location, facing northwest. Photos 6-8 provide an overview of the Location from northwest, north to northeast. Photos also show areas not reasonably needed for production on the Location have not been reclaimed.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 7: See comments under photo 6.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 8: See comments under photo 6.



Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 9: Photo taken from the southwest end of the Location, facing south. Photo shows BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 10: Photo taken from the southwest end of the Location, facing southeast. Photo shows BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC - 10433
Location ID: 383337



Photo 11: Photo taken from the access road on the north end of the Location, facing northwest. Photo shows BMPs to stabilize/protect slopes, and prevent off-site sediment transport are missing, or insufficient.