

Inspection Photos
Location Name: Chalk Bluffs 36-13H
Location ID: 420168



Photo 1 – Pumping Unit



Photo 2 – Wellhead, Stained Soil cleaned up

Inspection Photos
Location Name: Chalk Bluffs 36-13H
Location ID: 420168



Photo 3 – Unused Workover Rig Equipment



Photo 4 – Heater Treater

Inspection Photos
Location Name: Razor 29-2007
Location ID: 439422



Photo 5 – Tank Battery



Photo 6 – Tank Battery Sign