

Inspection Photos

Operator: Coral Production Corp, 20275

Lease: Christianson B 4-WD

Facility ID/API, 236911 / 05-121-09411



1. Lease sign



2. Wellhead/Braidenhead riser



Inspection Photos

Operator: Coral Production Corp, 20275

Lease: Christianson B 4-WD

Facility ID/API, 236911 / 05-121-09411



3. Central tank battery sign



4. Central Tank Battery



Inspection Photos

Operator: Coral Production Corp, 20275

Lease: Christianson B 4-WD

Facility ID/API, 236911 / 05-121-09411



5. Gun barrel and pump shed



6. Water injection pump shed



Inspection Photos
Operator: Coral Production Corp, 20275
Lease: Christianson B 4-WD
Facility ID/API, 236911 / 05-121-09411



7. Water tanks




8. Water tank with overflow to pit

Inspection Photos
Operator: Coral Production Corp, 20275
Lease: Christianson B 4-WD
Facility ID/API, 236911 / 05-121-09411



9. Overflowing to pit



10. Overflow from pit to buried tank

Inspection Photos

Operator: Coral Production Corp, 20275

Lease: Christianson B 4-WD

Facility ID/API, 236911 / 05-121-09411



11. Overflowing to 98% buried tank



12. Overflow from buried tank to surface discharge.



Inspection Photos

Operator: Coral Production Corp, 20275

Lease: Christianson B 4-WD

Facility ID/API, 236911 / 05-121-09411



13. Surface discharge to pond



14. North pond partially dry with deposits.

