

Issue Report

Christianson B #4-WD, 121-09411



Report created on December 15, 2020

Captured: December 4, 2020



Type	Count
Other	10

No.	Summary	Type	Created	Status
10	Christianson B-5 well	Other	Dec 15, 2020 at 3:43pm	Open
9	Mineral deposits on north end of surface pit.	Other	Dec 15, 2020 at 3:39pm	Open
8	Discharge from overflow tank to surface pond.	Other	Dec 15, 2020 at 3:38pm	Open
7	Pit overflow to buried tank on south end of pit	Other	Dec 15, 2020 at 3:36pm	Open
6	Water discharge from water tanks	Other	Dec 15, 2020 at 3:34pm	Open
5	Water tanks	Other	Dec 15, 2020 at 3:33pm	Open
4	Oil storage	Other	Dec 15, 2020 at 3:32pm	Open
3	Well injection pump shed	Other	Dec 15, 2020 at 3:32pm	Open
2	Gun Barrel, pump shed	Other	Dec 15, 2020 at 3:31pm	Open
1	Well	Other	Dec 15, 2020 at 3:30pm	Open

Other



No.	Summary	Created	Status
10	Christianson B-5 well	Dec 15, 2020 at 3:43 PM	Open
9	Mineral deposits on north end of surface pit.	Dec 15, 2020 at 3:39 PM	Open
8	Discharge from overflow tank to surface pond.	Dec 15, 2020 at 3:38 PM	Open
7	Pit overflow to buried tank on south end of pit	Dec 15, 2020 at 3:36 PM	Open
6	Water discharge from water tanks	Dec 15, 2020 at 3:34 PM	Open

5	Water tanks	Dec 15, 2020 at 3:33 PM	Open
4	Oil storage	Dec 15, 2020 at 3:32 PM	Open
3	Well injection pump shed	Dec 15, 2020 at 3:32 PM	Open
2	Gun Barrel, pump shed	Dec 15, 2020 at 3:31 PM	Open
1	Well	Dec 15, 2020 at 3:30 PM	Open

No. 1 OPEN

Captured: Dec 4, 2020 at 12:03pm



Type
Other

Lat/Long
39.76658, -102.96976

Summary
Well

Created
Dec 15, 2020 at 3:30pm by Craig Quint

No. 2 OPEN

Captured: Dec 4, 2020 at 12:03pm



Type
Other


Lat/Long
39.76794, -102.96748

Summary
Gun Barrel, pump shed

Created
Dec 15, 2020 at 3:31pm by Craig Quint

No. 3 OPEN

Captured: Dec 4, 2020 at 12:03pm



Type
Other

Lat/Long
39.76794, -102.96748

Summary
Well injection pump shed

Created
Dec 15, 2020 at 3:32pm by Craig Quint

No. 4 OPEN

Captured: Dec 4, 2020 at 12:03pm



Type
Other

Summary
Oil storage

Lat/Long
39.76794, -102.96748

Created
Dec 15, 2020 at 3:32pm by Craig Quint

No. 5 OPEN

Captured: Dec 4, 2020 at 12:03pm



Type
Other


Summary
Water tanks

Lat/Long
39.76775, -102.96714

Created
Dec 15, 2020 at 3:33pm by Craig Quint

No. 6 OPEN

Captured: Dec 4, 2020 at 12:03pm



Type
Other


Lat/Long
39.76775, -102.96714

Summary
Water discharge from water tanks

Created
Dec 15, 2020 at 3:34pm by Craig Quint

No. 7 OPEN

Captured: Dec 4, 2020 at 12:03pm



Type
Other

Lat/Long
39.76664, -102.96636

Summary
Pit overflow to buried tank on south end of pit

Created
Dec 15, 2020 at 3:36pm by Craig Quint

No. 8 OPEN

Captured: Dec 4, 2020 at 12:03pm



Type
Other

Lat/Long
39.76584, -102.96686

Summary
Discharge from overflow tank to surface pond.

Created
Dec 15, 2020 at 3:38pm by Craig Quint

No. 9 OPEN

Captured: Dec 4, 2020 at 12:03pm



Type
Other

Lat/Long
39.76639, -102.97036

Summary
Mineral deposits on north end of surface pit.

Created
Dec 15, 2020 at 3:39pm by Craig Quint

No. 10 OPEN

Captured: Dec 4, 2020 at 12:03pm



Type
Other

Lat/Long
39.76923, -102.96705

Summary
Christianson B-5 well

Created
Dec 15, 2020 at 3:43pm by Craig Quint