

# Construction and Stormwater Inspection

December 15, 2020

Operator: INCLINE OPERATING LLC- #10689

Location ID: 470899

Inspection Document #: 697502284

Weld County, CO

SESE Section 27 T6N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Hungenberg /Pad  
Location ID: 470899



**Photo 1.** Photo taken from the entrance of location, facing South. Photo illustrates has installed a ditch and berm BMP around the entire perimeter of location in conjunction with a sediment trap. Sound wall installation was being conducted at the time of this inspection. At the time of this inspection, there was no observed Form 2A posted at location.

Inspection Photos  
Location Name: Hungenberg /Pad  
Location ID: 470899



**Photo 2.** Photo taken from the entrance of location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: Hungenberg /Pad  
Location ID: 470899



**Photo 3.** Photo taken from the southwestern location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: Hungenberg /Pad  
Location ID: 470899



**Photo 4.** Photo taken from the southwestern location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: Hungenberg /Pad  
Location ID: 470899



**Photo 5.** Photo taken from the northwestern location, facing Northeast. Photo illustrates the Operator has temporarily stabilized the topsoil with equipment tracking.

Inspection Photos  
Location Name: Hungenberg /Pad  
Location ID: 470899



**Photo 6.** Photo taken from the northwestern location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: Hungenberg /Pad  
Location ID: 470899



**Photo 7.** Photo taken from the southeastern location, facing South. Photo illustrates the sediment trap installed with a temporarily stabilized outlet. This will likely be sufficient for winter conditions but this will not be sufficient for the monsoon season and to protect the irrigation ditch 14' feet to east of the location.

Inspection Photos  
Location Name: Hungenberg /Pad  
Location ID: 470899



**Photo 8.** Drone aerial imagery taken 12/15/2020.