

Inspection Photos
Location Name: Musser, B W "B" 19
Location ID: 312923



Photo 1. Overview of location taken facing west.



Photo 2. No bradenhead access apparent.

