



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Stagner 6      API: 05-103-07362**  
**Inspection: 700404589**







40.09897, -108.81593, 5149.8ft, 278°  
12/15/2020 01:07:34 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Pump jack.**

**Stagner 6      API: 05-103-07362**  
**Inspection: 700404589**





40.09897, -108.81593, 5143.8ft, 295°  
12/15/2020 03:16:15 PM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources


**Photo 4. Well.**

**Stagner 6      API: 05-103-07362**  
**Inspection: 700404589**



40.09898, -108.81591, 5144.2ft, 264°  
12/15/2020 01:07:15 PM





**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Photo 6. FLIR image of base of well.

Stagner 6      API: 05-103-07362  
Inspection: 700404589